

RECEIVED

JAN 28 1992

DIVISION OF
OIL GAS & MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) Jan 1991 To (mo./yr.) Jan 1992
2. DOGM File Number: M / 023023
3. Mine Name: Henry #1 and #2 Mine
4. Mineral(s) Mined: Gypsum
5. Legal Description (Location of Lands Affected):
SE 1/4, NW 1/4, Section 19, Township 15S, Range 1E
W1/2 NW 1/4, NE 1/4, Section 19, Township 15S, Range 1E
NW 1/4, SE 1/4, Section 19, Township 15S, Range 1E
6. Name of Operator or Company: H.E. Davis and Sons
7. Permanent Address: 525 W. Arrowhead Trail
Spanish Fork, Utah 84660

8. Company Representative (or designated operator):

Name: Harold E. Davis
Title: President
Address: 525 W. Arrowhead Trail Sp. Fk. Ut.
Phone: 798-7355

☐ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 31,464 tons
3. How much new or additional acreage was affected during past year? 1 1/2 Acres

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

Removal of 2 to 4 feet of overburden and mining gypsum.

The overburden was removed with a D-8 Cat. Dozer. Topsoil stored East of disturbed area. The volume of topsoil removed approx. 4,000 yds³. The volume of gypsum mined was approx. 12,000 tons.

5. How much acreage was reclaimed during past year? None

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

None

7. What is the total disturbed acreage at years end? 4 1/2 acres

8. Briefly summarize mining and reclamation planned for the upcoming year.

To cover disturbed area located in the south-east corner
of the pit, with topsoil and then seed. The area reclaimed
will be approx. 1 1/4 acres.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Harold E. Davis

Title of Operator: President

Signature of Operator: Harold E. Davis

Date: Jan. 27, 1992

jb
MR-AR